۲. .۳

Approved for Public Release Distribution Unlimited

PTPT Reportation 79-13
AFPEA Project No. 79-P7-49

07220V0

DWIGHT S. SHEETER
Mechanical Engineering Technician
Autovon 787-4234
Commercial (513)257-4234

Comparative Evaluation of Container Leak Test Procedures of Federal Test Method Standard 101B Method 5009


DUC FILE COPY

HQ AFALD/PTP
Air Force Packaging Evaluation Agency
Wright-Patterson AFB OH 45433

Jule 1979

95p.1

403519



own illimas

NOTICE

When government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related government procurement operation, the United States Government thereby incurs no responsibility whatsoever; and the fact that the government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any pate-ted invention that may in any way be related thereto. This report is not to be used in whole or in part for advertising or sales purposes.

ABSTRACT

This report presents an evaluation of Container Leak tests, i.e., the squeeze technique, (para 6.4), versus the vacuum chamber technique, (para 6.2), prescribed in method 5009-1 of Federal Test Method Standard 101-B. The squeeze test was found to be a suitable alternative to the vacuum chamber test for determining leaks in flexible self supporting containers sealed in atmospheric conditions.

Access	ionFor			
NTIS	Glašī			
DDC TAB				
Uninniumoed Li				
Justification				
Ву				
Distribution/				
Availability Codes				
	Availa.	id/or		
Dist	specia	al		
1				
1/1				
171				

STATEMENT TO STATE THE PROPERTY OF THE PROPERT

PUBLICATION DATE: 3 0 JUL 1979

PREPARED BY: Sweet Sheets
DWIGHT S. SHEETER

Mechanical Engineering Technician AF Packaging Evaluation Agency

REVISWED BY: Matchew C. Vantes

MATTHEW A. VENETOS Chief, Materials Engineering Div. AF Packaging Evaluation Agency APPROVED BY:

JACK E. THOMPSON Director

Director

AF Packaging Evaluation Agency

-i-

1. Objective

The purpose of this investigation was to evaluate Federal Test Method Standard 101B, Method 5009 squeeze test to determine if it is an acceptable alternative to the vacuum chamber test now required by the Air Force in contracts with Champion Spark Plug Company of Toledo Ohio.

2. Background

Champion Spark Plug Company requested San Antonio ALC to grant a waiver of the requirement for the Vacuum Chamber leak test in favor of the squeeze test for self supporting polyethylene tubes utilized for packing products delivered under contract with the Air Force.

Approval of the waiver would provide Champion Spark Plug with a less time consuming method of test and would also reduce the monetary expenditures for equipment required to accomplish the leak test

Sample containers were requested from the Champion Spark Plug Company. Six containers were provided; 2 samples with only one end sealed as received from the container supplier; 2 samples with both ends sealed; and 2 samples with jet engine ignitors enclosed and both ends sealed.

3. Package Construction

The containers were examined and found to be fabricated from a flexible l inch diameter polyethylene extrusion .026 inches thick and $5\ 1/2$ inches long with one end sealed by the container supplier and the second end sealed after product insertion by the contractor, Champion Spark Plug Company.

2000 High the control of the control

4. Test Procedures/Resul.s

- a. Vacuum Test A vacuum chamber test of one tube was performed in accordance with Federal Test Method Standard 101B, Test Method 5009, paragraph 6.2. The sample was submerged under one inch of water and placed in the high altitude chamber manufactured by the Atlas Engineering Co. of West Hartford Conn Model U16-90V. The chamber was evacuated to 9.72 inches of mercury. This provided a pressure differential between the air inside the tube and the air outside the tube of approximately 4.75 lbs per square inch. At this point the seal made by Champion Spark Plug failed. Escaping air caused a stream of bubbles to form in the water where the leak occurred.
- b. Squeeze Test A one inch diameter metal plug with a 1/4 inch tube passing through the center and protruding 1 1/2 inch was affixed with solder. Electrical tape was wrapped around the plug to provide a snug fit with the Champion container. This assembly was placed approximately ore half inch into the container and sealed with a hose clamp. The 1/4 inch tube was connected to a pressure gauge, (Heise H 32581), with a plastic tule approximately four inches long. All connections were clamped to prevent leaks. Three sample containers were evaluated. Sample #1 consisted of an empty container sealed at both ends. The end sealed by the container supplier was cut off and the prepared plug was inserted, sealed, and connected to the pressure gauge.

This tube was squeezed repeatedly. The pressure gauge showed a maximum of 5 pounds per square inch pressure with the average estimated at 4.5 pounds per square inch. This test was terminated after five squeezes at which time the tube end sealed by the Champion Spark Plug Co. failed.

Sample #2 consisted of a tube sealed at both ends, with ignitor inside. The end sealed by the Champion Spark Plug Co. was cut off and the prepared plug was inserted approximately one half inch and sealed with a hose clamp with the contents remaining with the tube. This assembly was connected to the pressure gauge and all connections were clamped. Repeated squeezes caused the gauge to show a high of 3.75 pounds per square inch with the average estimated at three pounds per square inch. No seal failure occurred.

The third tube, with an ignitor, inside and each end sealed was piercedwith a .0141 inch diameter wire. This tube was immersed in water and squeezed very slightly. The result was a stream of very small but highly noticeable bubbles forming at the puncture and rising to the surface of the water indicating a defective container.

5. Conclusion

Based on the results described above, it is concluded that the squeeze test is as effective as the vacuum chamber test for the identification of leaks in flexible packages of the type evaluated in this study.

`		
	•	
	D=0005D	
	DISTRIB	UTION LIST
	HQ USAF/LETN	
	Wash DC 20330	1
	Aviation Supply Office ATTM: TEP-A	
	Philadelphia PA 19111	1
		-
	Commander	
	US Army Natick R&D Ctr/DRXNM/EPS Natick MA 01760	1
	Hacter III 01/00	-
	NWC-Earle	
	Colts Neck NJ 07722	1
	DESC/LQP	
	1507 Wilmington Pike	
	Dayton, OH 45444	1
	JMPTC	
	Aberdeen Proving Ground MD 21005	2
	ADTC/SD3E Eglin AFB FL 32542	1
	egiin Arb rl 32542	1
	ADTC/SD3P	
	Eglin AFB FL 32542	1
	OO-ALC/DSTC	•
	Hill AFB UT 84406	1
	OC-ALC/D3P Tinker AFB OK 73145	1
	ITHEEL MED ON 19749	±
	SA-ALC/DSP	
	Kelly AFB TX 78241	1
	SM-ALC/DSP	•
	McClellan AFB CA 95652	1
		•
		3
		and the second s
ランプル インボニ 見 型 ・・・・・・		